



U.S. Department  
of Transportation

**Federal Aviation  
Administration**

CE-05-62  
June 27, 2005

# **SPECIAL AIRWORTHINESS INFORMATION BULLETIN**

Aircraft Certification Service  
Washington, DC

<http://www.faa.gov/aircraft/safety/alerts/>

*This is information only. Recommendations aren't mandatory.*

## **Introduction**

This Special Airworthiness Information Bulletin (SAIB) alerts you, owners and operators of **SOCATA - Groupe Aerospatiale (EADS) TBM 700 airplanes**, of excessive wear of the flap actuator drive nut due to grease contamination.

## **Background**

There have been two incidents regarding excessive wear of the flap actuator drive nut on EADS Socata TBM 700 aircraft. The wear, if not detected and corrected, could result in excessive wear of the flap actuator drive nut and result in an asymmetric lift condition with uneven flap deployment.

EADS Socata addressed the issue of excessive wear of the flap actuator drive nut in Mandatory Service Bulletin SB 70-118-27, dated May 2004. The European Aviation Safety Agency (EASA) issued Airworthiness Directive (AD) No. 2004-8063, dated July 27, 2004, and the Direction Générale de l'Aviation Civile (DGAC) issued AD F-2004-0134, dated August 4, 2004, to address this issue.

*AD F-2004-134 states as follows:*

## **1. EFFECTIVITY:**

EADS SOCATA TBM 700 airplanes, all serial numbers.

## **2. REASONS:**

An excessive wear of the flap inner actuator drive nut increased by grease pollution may lead to an improper play between the actuator threaded rod and the drive nut.

## **3. MANDATORY ACTIONS AND COMPLIANCE TIME:**

The following measures are rendered mandatory from the effective date of this AD:

Within the next 110 flight hours:

### **3.1. Inner actuators with less than 1200 hours Time in Service:**

Clean and lubricate the actuator threaded rod according to the paragraph C of the EADS SOCATA Service Bulletin 70-118-27, then repeat this operation every 110 flight hours.

### **3.2. Inner actuators with more than 1200 hours Time in Service:**

Check the play between the drive nut and the actuator threaded rod according to the paragraphs A & B of the EADS SOCATA Service Bulletin 70-118-27 then repeat this operation every 330 flight hours.

Clean & lubricate the actuator threaded rod according to the paragraph C of the EADS SOCATA Service Bulletin 70-118-27 then repeat this operation every 110 flight hours.

**4. REFERENCE PUBLICATION:**

Service Bulletin EADS SOCATA No 70-118-27 dated May 2004.

**5. EFFECTIVE DATE:**

August 14, 2004.

**6. REMARKS:**

For questions concerning the technical contents of this AD's requirements, contact:

EADS SOCATA  
Direction des Services  
Aéroport de Tarbes-Lourdes-Pyrénées  
65921 Tarbes Cedex 9  
FRANCE  
Tel.: +33 (0)5 62 41 73 00  
Fax: +33 (0)5 62 41 76 54

Or for the United States of America :

SOCATA AIRCRAFT, INC.  
North Perry Airport  
7501 South Airport Rd.  
Pembroke Pines, FL 33023  
UNITED STATES OF AMERICA  
Phone: 1 (954) 893 1400  
Fax: 1 (954) 964 0805

**7. APPROVAL:**

This AD is approved under EASA reference No 2004-8063 dated July 27, 2004.

**Recommendation**

We recommend that you do the following to address excessive wear of the flap actuator drive nut due to grease contamination:

- Inspect and service the flap actuator drive nut in accordance EADS Socata service bulletin, SB70-118-27, dated May 2004.
- If there are any instances of excessive wear of the flap actuator drive nut, report the following:
  - The flap actuator drive nut part number and serial number (if available).
  - The flap actuator drive nut time in service.
  - The aircraft serial number.
  - Send report to: Peter L. Rouse, Aviation Safety Engineer, Small Airplane Directorate; phone: (816) 329-4135; email: [peter.rouse@faa.gov](mailto:peter.rouse@faa.gov)

**For Further Information Contact**

Peter L. Rouse, Aviation Safety Engineer,  
Small Airplane Directorate; phone:  
(816) 329-4135; email: [peter.rouse@faa.gov](mailto:peter.rouse@faa.gov)